## **TABLE VII**

## **Fire Protection System Fees**

Number	Activity	Fee
1.	Fire Pumps (each pump)	
	a.) Review	\$341.09
	b.) Inspection	\$917.24
2.	Standpipe Systems (each stand pipe)	
	a.) Review	\$127.75
	b.) Inspection	\$256.77
3.	Underground Fire Service (each lateral)	
	a.) Review	\$90.69
	b.) Inspection	\$256.77
4.	Fire Sprinklers (each system)	·
	Base Fee	
	a.) Review	\$274.66
	b.) Inspection	\$274.66
	Plus each sprinkler head	421 1100
	a.) Review	\$2.74
	b.) Inspection	\$4.54
	, ·	Ψ4.04
В.	Fire Sprinklers Tenant Improvement:	
	Category 1: Affidavit 1 to 10 heads: (limited to arm-overs and drops with a	
	head location diagram for inspection reference)	
	Base Fee	
	a.) Review	\$0
	b.) Inspection	\$90.69
	Category 2: Affidavit 11 to 20 heads: (limited to arm-overs and drops in a	
	light hazard occupancy with a head location diagram for inspection	
	reference)	
	Base Fee	
	a.) Review	\$0
	b.) Inspection	\$183.97
	Category 3: Fire sprinkler system alterations that involve only changing	
	heads of the same performance characteristics and minor adjustments to	
	drop lengths:	
	Base Fee	
	a.) Review	\$0
	b.) Inspection	\$183.97
	Plus each sprinkler head	
	a.) Review	\$0
	b.) Inspection	\$2.74
	Category 4: Fire sprinkler system alterations or additions that don't fall	
	under Category 1, 2 or 3:	
	Base Fee	
	a.) Review	\$90.69
	b.) Inspection	\$183.97
	Plus each sprinkler head	4.00.0.
	a.) Review	\$0.88
	b.) Inspection	\$2.74
C.	Dry Pipe, Antifreeze, Pre-Action (each in addition to fire sprinkler	Ψ2.17
	system)	
	a.) Review	\$127.75
	·	
_	b.) Inspection	\$256.77
5.	Clean Agent System (CO2, FM-200, Inergen, etc.)	<b>.</b>
	a.) Review	\$457.34
	b.) Inspection	\$642.58

6.	Commercial Cooking Hood and Duct Protection (per new system)	
0.	a.) Review	\$329.59
	b.) Inspection	\$220.99
	Commercial Cooking Hood and Duct Protection Minor Revisions	Ψ220.00
	(Permit not required if modification is limited to normal maintenance,	
	replacing or reconfiguring heads and no increase in flow points used.)	
	Applicant to notify Fire Marshal's Office of location and extent of work.	
	a.) Review	\$0
	b.) Inspection	\$0 \$0
7.	Fire Alarm Systems – Minor (additions, no new panel, up to 10 devices)	ΨΟ
	Category 1: Affidavit 1-4 devices (limited to spot smoke or heat detectors,	
	horn/strobes, strobes, horns, mini-horns, manual pull stations or one	
	communication device)	
	a.) Review	\$0
	b.) Inspection	\$159.68
	Category 2: Modifications of up to 10 devices not qualifying for affidavit	*
	(e.g., additions, no new panel)	
	Base Fee	
	a.) Review	\$90.69
	b.) Inspection	\$183.97
	Plus each device	•
	a.) Review	\$3.67
	b.) Inspection	\$9.20
8.	Fire Alarm Systems – Major (new panel or 11+ devices, central station)	·
	Base Fee	
	a.) Review	\$274.66
	b.) Inspection	\$274.66
	Plus each device	
	a.) Review	\$3.67
	b.) Inspection	\$9.20
	RPERMITS	
9.	Underground Tank Demolition (each tank)	
	Flammable and combustible liquids – with reference diagram showing	
	a.) Review	\$0
	b.) Inspection	\$31.94
10.	Smoke Control Systems (up to 3 shafts)	
	Base Fee	
	a.) Review	\$550.60
	b.) Inspection	\$1,098.65
	Each additional shaft	<b>#</b> 400.07
	a.) Review	\$183.97
	b.) Inspection	\$366.63
	Other Smoke Control (atriums, malls, others)	
	Base Fee	<b>¢</b> EE0.60
	a.) Review	\$550.60
	b.) Inspection	\$1,098.65
	Each additional shaft a.) Review	¢402.07
		\$183.97 \$366.63
TRIP F		φ300.03
		¢67 74
11.	Trip Fee Assessment	\$67.71